


Legend

- Site Boundary
- + Turbine
- Infrastructure - Permanent
- Infrastructure - Temporary
- Proposed Earthworks
- Tile Extent/Figure Number
- Peatland Condition Assessment Study Area

Figure Title		
Peatland Condition Assessment (PCA) Study Area and Results		
Project Name		
Watchman Energy Park		
Project No./Filey ID		
1620016964 / REH2024N01805		
Date	Figure No.	Revision
February 2026	6.5	2.0
Prepared By	Scale	
KS	1:30,000 @A3	
Client		
Watchman Energy Park Ltd		





Legend

- Site Boundary
- Turbine
- Infrastructure - Permanent
- Infrastructure - Temporary
- Proposed Earthworks
- Peatland Condition Assessment Study Area

Peatland Condition Assessment Results

- Drained: Artificial
- Forested/Previously Forested
- Modified
- N/A (not peatland)

Figure Title
Peatland Condition Assessment (PCA) Study Area and Results


Project Name
Watchman Energy Park

Project No./Filey ID
 1620016964 / REH2024N01805

Date	Figure No.	Revision
February 2026	6.5.1	2.0


Prepared By	Scale
KS	1:10,000 @A3

Client
Watchman Energy Park Ltd



610000
609500
609000
608500
608000
607500

293500 294000 294500 295000 295500 296000 296500



Legend

- Site Boundary
- Turbine
- Infrastructure - Permanent
- Infrastructure - Temporary
- Proposed Earthworks
- Peatland Condition Assessment Study Area

Peatland Condition Assessment Results

- Actively Eroding
- Actively Eroding: Hagg/Gully
- Drained: Artificial
- ▲ Modified
- × N/A (not peatland)

Figure Title
Peatland Condition Assessment (PCA) Study Area and Results

Project Name
Watchman Energy Park

Project No./Filey ID
1620016964 / REH2024N01805

Date	Figure No.	Revision
February 2026	6.5.2	2.0

Prepared By	Scale
KS	1:10,000 @A3

Client
Watchman Energy Park Ltd

